

Emchem Glycol Spill

Photo Log

Description: Valve on tank where release of product occurred due to settling of tank.

Category: Site Photo

Latitude:

Date Taken: 10/11/2011

Longitude:

Tags:



Description: TCEQ contractor crews removing spilled product from the release area and ground where it had migrated.

Category: Site Photo

Latitude:

Date Taken: 10/11/2011

Longitude:

Tags:



Description: Drainage ditch located between property line and Rice Drier Road.

Category: Site Photo

Latitude:

Date Taken: 10/11/2011

Longitude:

Tags:



Description: Earthen berm placed in drainage ditch to contain product.

Category: Site Photo

Latitude:

Date Taken: 10/11/2011

Longitude:

Tags:



Description: Vacuum truck mobilized to the site to pump down product located in the four 18,000 gallon ASTs and transfer to Frac Tanks for temporary storage.

Category: Site Photo

Latitude:

Date Taken: 10/11/2011

Longitude:

Tags:



Description: Location of release from AST.

Category: Site Photo

Latitude:

Date Taken: 10/11/2011

Longitude:

Tags:



Description: Tank EBT located on east side of property.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: Tanks EBT and T-18.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: Tanks WBT and MBT located on west side of property.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: Eroded tank foundation.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: Eroded tank foundation.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: Various items inside metal building located on property.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: Containers located inside metal building.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: 55-gallon drums located inside metal building. Contents unknown.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: Numerous lab bottles containing unknown contents.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: Numerous lab containers with unknown contents.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: Bottles with unknown contents located inside laboratory.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: Laboratory.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: Various bottles containing unknown liquids located inside metal building.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



Description: Various items in building located on property.

Category: Site Photo

Latitude:

Date Taken: 10/12/2011

Longitude:

Tags:



